

4820 Westheimer Rd, Houston, TX 77027  
Phone: (713) 555-XXXX | companynamellc@gmail.com  
License: TFS-44444 | EIN: 84-0000000

### SERVICE DETAILS

Customer:	Golden Dragon Chinese	Date:	Mar 22, 2026
Address:	890 Westheimer Rd, Houston TX	Technician:	Mike Johnson (#IKECA-4521)
		Next Due:	Jun 21, 2026

### COMPONENTS CLEANED

Hood Canopy	CLEANED
Filters (Baffle/Mesh)	CLEANED
Plenum	CLEANED
Ductwork (Horizontal)	CLEANED
Ductwork (Vertical)	CLEANED
Access Panels	CLEANED
Exhaust Fan & Housing	CLEANED
Rooftop Discharge	CLEANED
Backsplash / Wall	CLEANED
Grease Gutters & Trays	CLEANED

### COMPONENT CONDITIONS

Filters	GOOD
Ductwork	GOOD
Access Panels	GOOD
Fan Belts	GOOD
Hinge Kits	GOOD
Duct Seams/Joints	GOOD

### AREAS NOT CLEANED / INACCESSIBLE

All areas accessible — no exclusions

### DEFICIENCIES

No deficiencies found

## BEFORE PHOTOS

**IMAGE BEFORE CLEANING**

Hood 1

## AFTER PHOTOS

**IMAGE AFTER CLEANING**

Filters

### NFPA 96 CERTIFICATION

This kitchen exhaust system has been cleaned in accordance with NFPA 96 standards.

All accessible areas of the system have been cleaned to bare metal. Any areas not cleaned are noted above.

This report serves as the official record of service for compliance and insurance purposes.

Technician: Mike Johnson

Date: Mar 22, 2026

Customer: Customer/Manager Signature

